

Project Type:

Window Investigation
Window Replacement
Construction Administration

Building Address:

75 3rd Avenue
New York, NY

Building Owner:

New York University

Building Manager:

New York University

Building Facts:

Year Built: 1988
Height: 14 Stories
Plan Dimensions: 206' x 347'
Usage: Residential/Institutional

Scope of Services:

Performed preliminary window survey to investigate various window conditions. Currently developing window specifications for replacement windows to be reviewed by New York University. Construction administration services for the façade restoration are scheduled to take place in summer of 2020.

